TRUE RMS Installation Testers BENNING IT 115, IT 130
the perfect solution for efficient testing

Features BENNING IT 115, BENNING IT 130

- all measuring functions can be selected directly by means of a rotary switch
- graphic display and help function with connecting diagram
- current supply by means of 6 NiMH storage batteries (AA) with charger

Additional functions BENNING IT 130
in addition to the BENNING IT 115:

- testing of universal current-sensitive RCDs of type B/B+
- measured value memory covering four levels (object/block/fuse/measuring point) for up to 1800 measurements
- bidirectional USB/ RS 232 interfaces
- BENNING PC-Win IT 130 software included
- including "Commander" probe tip with "TEST" and "MEM" keys as well as bright LED measuring point illumination
- connection for barcode scanner for identifying the measuring point and renaming the storage location
- current measurement (TRUE RMS) by means of current clamp adapter (optional)
- illumination measurement by means of lux sensor (optional)

Logging software with Test Log according to ZVEH BENNING PC-Win IT 130

- creation and transmission of installation structures to the BENNING IT 130 for efficient periodic testing
- download of measured values and logging by means of test reports and ZVEH test certificates

Professional accessories

- "Commander" probe tip (optional for BENNING IT 115)
- "Commander" test plug for shock-proof socket (optional)

"Commander" probe tip*
044155

"Commander" test plug
044149

044148

044039
Example figure

Testing of universal current-sensitive RCDs of type B

IT 130

044038

Test log according to ZVEH

Scope of delivery BENNING IT 130

044111

Optional accessories

		item no.	applicable for
earthing set (2 earth rods, 3 test cables)	2 x 20 m, 1 x 4.5 m	**044113**	IT 115/IT130
measuring line BENNING TA 5	l = 40 m	**044039**	IT 115/IT130
CEE measuring adapter (V/rotary field)	16 A, 5-polig	**044148**	IT 115/IT130
"Commander" test plug	shock-proof sockets	**044149**	IT 115/IT130
"Commander" probe tip*	4 mm tip	**044155**	IT 115/IT130
current clamp adapter BENNING CC 3	0.2 A - 300 A AC/DC	**044038**	IT 130
BENNING Luxmeter type B	0.01 lux - 20 klux	**044111**	IT 130
barcode scanner with PS/2 connector	–	**009371**	IT 130

* Included in the scope of delivery of the BENNING IT 130

009371

044113